



































































# VENTURA RIVER WATER DISTRICT

**DATE:** April 20, 2022  
**TO:** Directors  
**FROM:** Bert J. Rapp, P.E. General Manager  
**SUBJECT:** WATER AND DISTRICT UPDATE

**Wells & Production**

The static aquifer level at Well #2 on April 1, 2022 was at elevation 530, the level dropped 0.1 feet since the first of last month. The aquifer is 4.4 feet below the 30-year average for April 1<sup>st</sup>.

Well #1 is pumping 1,031 gpm up 19 gpm from last month. Well #7 is pumping 774 gpm up 14 gpm from last month, Well #6 was pumped for three days to test the diluted sodium hypochlorite. Wells #2, #3 & #4 were not on-line in March.

**Usage**

Sales dollars billed on March 31, 2022 amounted to \$169,958, \$34,273 over budget for March. Last year we billed \$148,443 during the same period. Water sold in March 2022 amounted to 25,265 HCF, a decrease of 15% below the 29,667 HCF sold in March 2013.

Charts are enclosed to depict the ground water status and water usage. On April 1, 2022, Lake Casitas level was 34.5% of full capacity at elevation 489.14, with storage of 82,146 AF. The lake decreased 0.3%, dropped 0.6 feet and decreased 657 AF since last month even with the 2-inch rainfall on March 28<sup>th</sup>.

ET adjustment: The ET was increased 26% for the March 31<sup>st</sup> water bill because ET was above average for the period. This increases the irrigation portion of the customer's water monthly water budget.

**Tico Merger Application to Casitas MWD**

The Casitas MWD approved the Tico Merger with Ventura River Water District on March 23, 2022.

## CUSTOMER COMPLAINT LOG

DATE	LOCATION / ADDRESS	Leak		OTHER / DESCRIPTION	FINDINGS COMMENTS
		VRWD	CUSTOMER SIDE		
3/11/2022	1135 Lake St			x	Broken AMS. Replaced AMS
3/14/2022	54 Calle El Prado	x			Service line leak.Replaced service line
3/16/2022	Barbara st and HW33	x			Drill Rig drilled through 8 inch main.Shut down water and fixed main.flushed and sampled.
3/17/2022	109 Alto Dr			x	Leak at bottom of AMS do to vehicle hitting box months earlier.Replaced AMS















