


# VENTURA RIVER WATER DISTRICT

## CURRENT GROUND WATER LEVEL

AS OF: **June 1, 2019**



**Critical Static Level**  
Only two wells out of  
four able to pump.

**Definitions**

**Static Level:** is the level of water in the well when no water is being taken (pumped) from the well.

**Pumping Level:** is the level of water in the well during pumping.

**Critical Satic Level:** is the level where many of our wells can no longer pump water and we must use much more water from Lake Casitas.

**ALWAYS CONSERVE WATER!**

**Rainfall**

**AVERAGE ANNUAL FAINFALL - 23"**

**RAINFALL SINCE OCTOBER 1, 2018**  
**27.3"**

**40-YEAR AVERAGE RAINFALL**  
**SINCE OCTOBER 1ST**  
**22.5"**