


**VENTURA RIVER WATER DISTRICT
CURRENT GROUND WATER LEVEL**

AS OF: October 1, 2021



**Critical Static Level
Only two wells out of
five able to pump.**

Average February 1st Static Water Level -53.9 Feet

Static Water Level, October 1, 2021 -67.7 Feet

Pumping Level

Pump Suction

Definitions

Static Level: is the level of water in the well when no water is being taken (pumped) from the well.

Pumping Level: is the level of water in the well during pumping.

Critical Satic Level: is the level where many of our wells can no longer pump water and we must use much more water from Lake Casitas.

ALWAYS CONSERVE WATER!

Rainfall

AVERAGE ANNUAL FAINFALL - 23"

RAINFALL SINCE OCTOBER 1, 2020
6.1"

40-YEAR AVERAGE RAINFALL SINCE OCTOBER 1ST
23"